Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	92575	((force load stress strain compress\$4 tensi\$3) near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 09:54
L2	3273	1 and (second two pair other another upper lower) near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:57
L3	337	2 and (spring resilien\$4 ealstic\$4 ) near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 08:50
L4	224	3 and (axis direction orientation coaxi\$4).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:47
L5	206	4 and spring.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 08:49
L6	7	4 and spring near2 constant.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 08:49
L7	43	4 and spring near2 constant .	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/08/14 08:50
L8	8	7 and coil.clm	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 08:50

L9	. 2	2 and constant near2 (spring resilien\$4 ealstic\$4) near3 (housing casing casting protecting covering). clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 08:51
L10	7	2 and constant near2 (spring resilien\$4 ealstic\$4 ) near3 (housing casing casting protecting covering)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON ·	2007/08/14 09:29
L11	72	2 and coaxial\$4 near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:39
L12	10	3 and coaxial\$4 near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:42
L13	6	3 and induct\$5.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:47
L14	2510361	1 and (second two pair other another upper lower) near3 (force load) introdu\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:44
L15	120	1 and (second two pair other another upper lower) near3 (force load) near3 introdu\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:45
L16	12	2 and (second two pair other another upper lower) near3 (force load) near3 introdu\$5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 10:17

117	1000	2 and (avia discation and tot)	116 000:10	00	0::	2007/20/4 / 22 /=
L17	1890	2 and (axis direction orientation coaxi\$4).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:47
L18	54	17 and induct\$5.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:58
L19	20	18 and core	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:47
L20	165	2 and (force load ) near3 (applying exert\$5 excert\$4 introducing implement\$4) near3 (plurality two second t multipl\$5 couple double pair other upper lower another ).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 09:52
L21		20 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:12
L22	10	20 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:01
L23	35	1 and coaxial\$4 near3 (second two pair other another upper lower) near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 10:14
L24	0	23 and induct\$5.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2007/08/14 09:58

		LAST Scarci				
L25	28	2 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:26
L26	9685	(induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:13
L27	2602	26 and (core)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:13
L28	0	27 and coaxial\$4 near3 (second two pair other another upper lower) near3 (housing casing casting protecting covering).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 10:14
L29	10	2 and 27	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 10:23
L30	8	("4827240" "6087598" "6129168" "63 23443").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:00
L31	1052	1 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 10:26
L32	.23	31 and seat.clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 10:28
L33	2	("4827240").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:02

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L34	1	33 and conduct\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:06
L35	2	("6087598").PN.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:02
L36	0	35 and conduct\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:06
L37		35 and induct\$4	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/08/14 11:11
L38	296	(73/161).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/08/14 12:30
L39	0	38 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR .	ON	2007/08/14 12:31
L40	2	38 and (induct\$4 near3 (measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4))	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/08/14 12:31